



WAX RECOMMENDATION

EVENT: Hanson Hills Michigan Cup Marathon
Grayling, Michigan - Saturday, February 16th

FREESTYLE

Forecast: Friday night low -1 degree F. Overnight snow anticipated.

Base Prep: Clean skis with SWIX CH10 or SWIX Base Prep 99 - scrape and brush using SWIX Course Bronze Brush(T0158) or SWIX Fine Steel Brush (T0192). Apply a layer of NEW SWIX MB77 Molly Base Prep. Scrape and brush. Clean kick zone with Swix base cleaner and Fiberlene, sand kick zone with 100grit sandpaper

Structure: Extra Fine Linear .25mm structure. Use SWIX Super Riller (T401).

GLIDE WAX - FAST

Race Wax: Apply SWIX CH4, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

* Repeat above for even faster skis!

GLIDE WAX - FASTER

Base Race Wax: Apply CH4, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

* Repeat above for even faster skis!

Race Wax: Apply LF4, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

Glide Wax - Wicked Fast

Base Race Wax: Apply SWIX LF4, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

* Repeat above for even faster skis!

Race Wax: Apply SWIX LF3 Powder, scrape and brush using SWIX Medium Bronze Brush (T1620) or SWIX Fine Steel Brush (T0192). Polish using SWIX Blue Nylon Brush (T160).

For detailed application instructions check out the
Swix School of Waxing at

SWIX[®] **school.com**